



FABBRICATO

10



INGRESSO SCALA

ASCENSORE






INGRESSO ALLOGGIO



INGRESSO



INGRESSO



SOGGIORNO



SOGGIORNO

BALCONE





CUCINA

CUCINA





DISIMPEGNO

A photograph of a narrow hallway with yellow walls and a brown tiled floor. The floor is stained and has some debris on it, including a white bottle and some crumpled paper. The walls are slightly peeling and the lighting is dim.

DISIMPEGNO



BAGNO



BAGNO



CAMERA



CAMERA

CAMERA



CAMERA





INGRESSO CANTINA



CANTINA